



WCF Servis Sağlayıcısını Değiştirme

Şu anda, VigorRouter'ın iki Web Content Filter (WCF) servis sağlayıcısı var, bunlar BPjM ve Cyren. Network Administrator, LAN kullanıcılarının yasak kategorideki web sitelerine erişmelerini önlemek için bir seferde bir WCF servis sağlayıcısı seçebilir. Servis sağlayıcıyı değiştirmek için, Network Administrator'un bu değişikliği MyVigor web sitesinde gerçekleştirmesi gerekir.

Lütfen, Router sayfasının "Activate" URL'sinden MyVigor web sitesine bağlanmasının gerekli olduğunu unutmayın. WCF servis sağlayıcısının nasıl adım adım değiştirileceğini açıklayacağız. Lütfen, bu tür servis sağlayıcıların değiştiğine dikkat edin; Network Administrator'un geçerli lisans süresi boyunca uyarlanabilir servisi seçmesine yardımcı olmak, ancak lisansın geçerliliğini uzatmamaktır.

- 1. Router'inizin WUI'sine giriş yapın ve ardından CSM >> Content Filter Profile sayfasına gidin.
- 2. Bu sayfanın sağ üstündeki "Activate" bağlantısını tıklayın.



Vigor3900 / 2960 / 300B kullanıyorsanız, lütfen Objects Setting >> Web Category Object >> Content Filter License'a gidin, "Activate URL" ye tıklayın.

Objects Setting >> Web Category Object >> Content Filter License				
Web Category Obje	ct Content Filter License	Query Server		
Liconeo	Activate LIRI			
License.	ACTIVATE ORL			
Enable :	enable			
Service :	BPjM			
Start Date :	2017-05-09			
Expire Date :	2018-05-09			

3. pop-out pencereden MyVigor'a giriş yapın.







4. Değiştirmek istediğiniz servis sağlayıcı rulosundaki "On" düğmesine tıklayın.

evice Infor evice Name : FAE280 rial Number : 163002 Model : Vigor28	mation 50 1926186 360 Series				Rename Transfer	Back
Device	e's Service	Expired License				
Service	Provider	Action	Status	Start Date	Expired Date	Note
🕷 WCF	BPjM	Renew	On	2017-04-17	2018-04-17	-
WCF	Cyren	Renew	On	2017-04-17	2017-05-17	-
😤 APPE	DT-APPE	Renew	On	2017-03-27	2018-03-27	-
	evice Infor evice Name : FAE280 rial Number : 163002 Model : Vigor28 Device Service WCF WCF WCF APPE	evice Information evice Name : FAE2860 rial Number : 163002926186 Model : Vigor2860 Series Device's Service Service Provider WCF BPjM WCF Cyren APPE DT-APPE	evice Information evice Name : FAE2860 rial Number : 163002926186 Model : Vigor2860 Series Device's Service Expired License Service Provider Action WCF BPjM Renew WCF Cyren Renew WCF DT-APPE Renew	evice Information evice Name : FAE2860 rial Number : 163002926186 Model : Vigor2860 Series Device's Service Expired License Service Provider Action Status WCF BPjM Renew On WCF Cyren Renew On WCF DT-APPE Renew On	evice Information evice Name : FAE2860 rial Number : 163002926186 Model : Vigor2860 Series Device's Service Expired License Service Provider Action Status Start Date WCF BPjM Renew Image: Onit Service 2017-04-17 WCF Cyren Renew Image: Onit Service 2017-04-17 WCF DT-APPE Renew Image: Onit Service 2017-03-27	evice Information evice Name: FAE2860 rial Number: 153002926186 Model: Vigor2860 Series Device's Service Expired License Service Provider Action Status Start Date Expired Date WCF BPjM Renew Image: Service 2017-04-17 2018-04-17 WCF Cyren Renew Image: Service 2017-04-17 2017-05-17 WCF DT-APPE Renew Image: Service 2017-03-27 2018-03-27

5. Aktivasyon başarı sayfasına yönlendirileceksiniz.

DrayTek Service Activation

Service Name	Start Date	Expire Date	Status
Web Content filter	2017-04-28	2017-05-28	Cyren
APP Enforcement			Not Activated
DDNS			

Please check if the license fits with the service provider of your signature. To ensure normal operation for your router, update your signature again is recommended.

Copyright © DrayTek Corp. All Rights Reserved.

Vigor3900 / 2960 / 300B kullanıyorsanız, sayfa şöyle olacaktır:

License Service Provider Cyren			
License Status	enable		
License Url	myvigor.draytek.com		
License Start Date	2017-05-09		
License Expired Date	2017-06-08		

Content Filter License Register is Success, Please Connect to <u>http://192.168.193.13</u>

8. WCF servis sağlayıcısının başarıyla değiştirildiğini onaylamak için lütfen VigorRouter'ınızın WUI'sine tekrar gidin.

